

POWER TRANSMISSION REPORT

TROUBLE SHOOTING FOR SUMEET, INDIA'S FIRST INDIGENOUS FRONT LOADING WASHING MACHINE.

Issue

We were called for a severe issue due to the wrong flat belt supply to Sumeet. Belt taking drive from twin speed motor for washing and spin cycle was recommended by a belt manufacturer having German collaboration. This belt was one of the major issues for this machine as it used to slip & had a short life.

Solution

We did our best in trying to give a high grip flexible flat belt working for about 2 years. We gave hundreds of belts to try to help resolve the issue.

